

Is there any change in the production equipment or layout of the factory? ?

Electricity, Fire Alarm




- Electricity increases, decreases, changes
- Electrical equipment is old, has many breakdowns, has many power outages, and shocking
- Is the wiring or board hot?
- Are you well-prepared for a fire?

Air Conditioning, Sanitary, Fire Fighting



- Is ventilation in the factory okay? (Corona virus measures)
- The air conditioner does not work, the room is hot
- Water leak
- When a fire happening, are the fire extinguish measures perfectly?

Plant, Civil




- Equipment transmission, installation, relocation, removal
- Equipment foundation, pit
- Pedestals addition, relocation, removal
- Works related with the above
- Partition extension, change, removal
- Clean Room, Explosion-proofed Room, Cold storage

Energy Saving, Environmental Improvement



- Energy Visual Control (Mieruka)
- Renewal energy-saving equipment
- Cooling water, coolant elementless filter
- Improvement of septic tank drainage water quality



If you have any problems, please contact Taiyo Sinar

Representatif : TEGUH P
 e-mail : teguhp@tsrt.co.id
 HP : 0812-1076-564



PT TAIYO SINAR RAYA TEKNIK

タイヨーシナール ラヤ テクニク

(Subsidiary Sumitomo Densetsu Co., Ltd.)

Please feel free to contact us for orders and consultations:

Head Office: SUMMITMAS I 7th Floor
 Technical Center: Cibitung

021-5253400
 021 - 88325503

MEP: Ito 0812-1002-075
 Plant: Sano 0811-1803-367
 Civil: Sano 0811-1803-367